











35840

H2210

(1)	(2)	(3)	(4)	(5)	(6)
	 X2	 X5			 X2 4X12  X2 6X30  X3 8X30  M4  X4 6X40  X4 6X35  X6 6X14  M6  M5

A	B	C	
	①: Step1 assemble Arm  ②: Step2 assemble Mechanism  ③: Step3 assemble Back 	 	

WENCHEN